

Boundary Coordinates on MGM 2008

Point No.	Easting (mE)	Northing (mN)	Description
1	573841.978	7778504.063	iron peg fixed on site
2	573875.869	7778481.844	iron peg fixed on site
3	573918.517	7778437.402	iron peg fixed on site
4	573926.068	7778412.768	iron peg fixed on site
5	573960.583	7778402.928	iron peg fixed on site
6	573981.582	7778364.497	iron peg fixed on site
7	573994.838	7778362.209	iron peg fixed on site

Boundary Coordinates on LGM

Point No.	Easting (mE)	Northing (mN)	Description
1	264824.165	370632.634	iron peg fixed on site
2	264858.142	370610.522	iron peg fixed on site
3	264900.954	370566.210	iron peg fixed on site
4	264908.591	370541.593	iron peg fixed on site
5	264943.315	370532.186	iron peg fixed on site
6	264964.286	370493.495	iron peg fixed on site
7	264977.419	370491.252	iron peg fixed on site

MINISTRY OF HOUSING AND
LAND USE PLANNING
SURVEY DIVISION

Title:

Plan showing Fountain Bay Brachois and its Reserves at Pointe des Lascars

Date	DWG Ref.	Scale :
Nov 2024	1319-2024	1 / 1500

Edited by : CARTOGRAPHY SECTION