



REPUBLIC OF MAURITIUS

**Ministry of Shipping, Rodrigues & Outer Islands
4th Floor, New Government Centre
PORT LOUIS**

NOTICE TO MARINERS Ref: INS 01 of 2005

Title : ISPS Code-Contact details for Ship Security Alert System (SSAS).

Notice to Owners, Managers, Masters of Mauritian flagged Vessels

1. In accordance with Regulation XI-2/6 of the SOLAS 74 Convention, (as amended), all ships engaged on International voyages must be provided with a Ship Security Alert System in accordance with the time schedule as indicated in the Table below.

	<i>Type of Vessel</i>	<i>Date of Construction</i>	<i>Compliance Date</i>
A	All ships constructed	On or after 1 July 2004	Upon delivery
B	Passenger ships Oil tankers Chemical tankers Gas carriers Bulk carriers, Cargo and High-Speed Craft of 500gt and upward.	Before 1 July 2004	No later than first survey of the radio installation after 1 July 2004
C	Other cargo ships of 500gt and upwards including self- propelled Mobile offshore drilling units	Before 1 July 2004	No later than first survey of the radio installation after 1 July 2006

2. The ship security alert system when activated must transmit a ship-to-shore security alert to the ship owner or management Company as well as to The Mauritius Radio Services.
The Inmarsat-C no of the Mauritius Radio Services is : 422800213.
3. The SSAS must be programmed in such a way that when it is activated, the Security Alert shall include the IMO number and the Call Sign of a ship.
4. All those concerned are reminded that when a ship is deleted from the Mauritian registry, the company shall immediately make all necessary arrangements for the reprogramming of the SSAS, as appropriate.

**Director of Shipping
Port Louis
February 2005**